

## COLOUR FASTNESS

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	LIGHT AS2001.4.21 60HRS	RUBBING AS2001.4.3		WASHING 40oc AS2001.4.15 TEST J2				WATER AS2001.4-E01				PERSPIRATION AS2001.4-E04				
		C.C	Dry	Wet	C.C	S.Co	S.Pa	S.PI	C.C	S.Co	S.Pa	S.PI	C.C	S.Co	S.Pa	S.PI
WHITE	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

- C.C: Colour Change.  
S.Co: Staining on Cotton.  
S.Pa: Staining on Nylon.  
S.PI: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		

SUBLIMATION TEST RESULTS	
LENGTH %	2%
WIDTH%	2%

Sublimation bases can react differently from machine to machine. Please ensure you test each fabric as a variation may occur due to machine settings and paper variation. Recommended sublimation procedure:

- 40 seconds
- 195-205 degrees
- No higher than 205

NOTE: 3-4% Shrinkage is deemed acceptable depending on the fabric type and knit construction.