

## COLOUR FASTNESS

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	LIGHT AS2001.4.21	WASHING AS2001.4.15-2006	WATER AS2001.4-E01				PERSPIRATION AS2001.4-E04				RUBBING AS2001.4.3	
	C.C	C.C	C.C	S.Pa	S.Co	S.PI	C.C	S.Pa	S.Co	S.PI	Dry	Wet
WHITE	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
CHALK	3-4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
EGGSHELL	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
JET BLACK	4-5	4	4-5	4	4-5	4-5	4-5	4	4-5	4-5	4	3
CLOUD	4-5	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
HONEY	5	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
CINNAMON	5	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
LILAC	4	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
GERANIUM	4	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
SEASHELL	5	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
STONEWASH	5	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
ICY MINT	5	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5
EMPRESS	5	4	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4-5	4

- C.C: Colour Change.  
S.Co: Staining on Cotton.  
S.Pa: Staining on Nylon.  
S.PI: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		