

COLOUR FASTNESS

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	LIGHT	RUBBING		WASHING			WATER			PERSPIRATION			SALT WATER		CHLORINE SENSITIVITY	
	AS2001.4.21	AS2001.4.3		AS2001.4.15 J2 40 °C)			AS2001.4-E01			AS2001.4-E04			AS2001.4.E02		AS2001.4.5	
	C.C	Dry	Wet	C.C	PE	PA	C.C	PE	PA	C.C	PE	PA	C.C	PA	100mg/L	20mg/L
WHITE	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
SKINTONE	4	4-5	4	4-5	4	4	4-5	4-5	4	4-5	4-5	4	4-5	4	4-5	4
BLACK	5-6	4	4-5	4-5	3-4	3	4-5	4	3	4-5	3-4	3	4-5	3	4-5	4-5

- C.C: Colour Change.
- S.Co: Staining on Cotton.
- S.Pa: Staining on Nylon.
- S.Pl: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		