

## COLOUR FASTNESS

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	LIGHT AS2001.4.21 60 HRS		WASHING AS2001.4.15 TEST J1 (40 °C)		WATER AS2001.4 E01			SALT WATER AS2001.4 E02			PERSPIRATION AS2001.4 E04			CHLORINE SENSITIVITY	
	C.C	C.C	S.Co	S.Pa	C.C	S.Co	S.Pa	C.C	S.Co	S.Pa	C.C	S.Co	S.Pa	50mg/l C.C	100mg/l C.C
TUXEDO	6	4-5	4	2-3	4-5	4	3-4	4-5	4-5	3-4	4-5	4	3-4	4-5	4-5

- C.C: Colour Change.
- S.Co: Staining on Cotton.
- S.Pa: Staining on Nylon.
- S.Pl: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		