

COLOUR FASTNESS:

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	WASHING AATCC 61			PERSPIRATION AATCC 15		RUBBING AATCC 8		LIGHT AATCC 16	CHLORINE AATCC 162	SEAWATER AATCC 106	
	C.C	S.Pa	S.PI	C.C	Stain	Dry	Wet	C.C	C.C	C.C	Stain
BLACK	4	4	4	4	4	3-4	2-3	3	4	4	3
BOTANICAL	4	4	4	4	4	3-4	2-3	3	4	4	3
BOYSENBERRY	4	4	4	4	4	3-4	2-3	3	4	4	3
CAFE	4	4	4	4	4	3-4	2-3	3	4	4	3
CHAMPAIGNE PINK	4	4	4	4	4	3-4	2-3	3	4	4	3
GRAVEL	4	4	4	4	4	3-4	2-3	3	4	4	3
HAZE	4	4	4	4	4	3-4	2-3	3	4	4	3
MIDNIGHT	4	4	4	4	4	3-4	2-3	3	4	4	3
POWDER BLUE	4	4	4	4	4	3-4	2-3	3	4	4	3
SUGAR PLUM	4	4	4	4	4	3-4	2-3	3	4	4	3
WHITE	4	4	4	4	4	3-4	2-3	3	4	4	3

- C.C: Colour Change.
- S.Co: Staining on Cotton.
- S.Pa: Staining on Nylon.
- S.PI: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		